

MONUMENT RECORD


Corner I.D. #

U-7

STATE OF INDIANA - COUNTY OF MONROE

Section Twelve (12), Township 9 North, Range 1 West

Monument Description & Remarks: Found Sandstone Stone w/"X" at West 1/4
Corner. Stone is on steep hill and was loose & leaning. Stone was firmed
up & straightened; cairn of rocks placed around base. Survey maker sign set



State of Indiana
County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; and the above data is given under my hand and seal this 3rd day of May, 1995 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Office of Monroe County Surveyor
United States Government Agency

Monroe County Surveyor
Title

Field Book:

95-01

Page:

33